

CONSTRUCTION EQUIPMENT VOLVO A40G 352198 - FRONT AXLE



Sample No: VCP312940

Oil Type: MOBIL MOBILUBE HD 80W90

Report Id: SCHGRE [WUSCAR] 05965737 (Generated: 10/03/2023 11:44:18) Rev: 1

Job No:

SAMPLI	E INFORMATION			
Sample Number		VCP312940	VCP405996	
Sample Date		06 Sep 2023	19 Jun 2023	
Machine Hours		4393	3898	
Oil Hours		495	239	
Oil Changed		Not Changd	Changed	
Sample Status		NORMAL	ATTENTION	
OIL CON	IDITION			
Visc @ 40°C	cSt	131	<u></u> 50.2	
V13C @ 40 C	CSt	131	<u> </u>	
VOLVO				
CONTAI	MINATION			
Silicon	ppm	4	2	
Sodium	ppm	■ 0	3	
Potassium	ppm	■<1	2	
WEAR N	METALS			
Iron	ppm	52	7 6	
Copper	ppm		- <1	
Lead	ppm	■0	0	
Tin	ppm	■ 0	0	
Aluminum	ppm	■<1	- <1	
Chromium	ppm	■<1	- <1	
Molybdenum	ppm	2	- <1	
Nickel	ppm	■<1	0	
Titanium	ppm	0	0	
Silver	ppm	0	0	
Manganese	ppm	1	_2	
Vanadium	ppm	0	0	
VOLVO				
ADDITIV	VES			
Calcium	ppm	203	4 3	
Magnesium	ppm	18	0	
Zinc	ppm	101	<u>14</u>	
Phosphorus	ppm	■1070	2491	
Priospriorus	ρριιι			
Barium	ppm	■0	0	



SCHILDBERG CONSTRUCTION COMPANY

PO BOX 358 GREENFIELD, IA US 50849 Contact: SCOTT ARMSTRONG sarmstrong@schildberg.com T: (641)743-8237 F: (641)743-2486

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SCHGREUnique No:10672288Signed:Wes DavisReport Date:02 Oct 2023



CONSTRUCTION EQUIPMENT





GRAPH

