



# CONSTRUCTION EQUIPMENT

607681 HERC VOLVO A30G 753403 - TRANSMISSION (AUTO)



**Sample No:** VCP440273  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 607681 HERC



**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## SAMPLE INFORMATION

Sample Number	VCP440273	---	---	---
Sample Date	22 Sep 2023	---	---	---
Machine Hours	589	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	■ 28.7	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	■ 14	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 3	---	---	---



## WEAR METALS

Iron	ppm	■ 14	---	---	---
Copper	ppm	■ 14	---	---	---
Lead	ppm	■ <1	---	---	---
Tin	ppm	■ 3	---	---	---
Aluminum	ppm	■ 12	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ 0	---	---	---
Nickel	ppm	■ 1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	■ 0	---	---	---
Manganese	ppm	■ 3	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	68	---	---	---
Magnesium	ppm	■ <1	---	---	---
Zinc	ppm	■ 3	---	---	---
Phosphorus	ppm	■ 182	---	---	---
Barium	ppm	■ 0	---	---	---
Boron	ppm	■ 81	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO0096  
**Unique No:** 10672347  
**Signed:** Don Baldrige  
**Report Date:** 03 Oct 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

