

## **CONSTRUCTION EQUIPMENT**

SWA374776 HITACHI ZW550-6 005203 - REAR RIGHT FINAL DRI

Sample No: VCP441767

**Oil Type:** GEAR OIL SAE 80W90

**Job No:** SWA374776

SAMPLE	E INFORMATIO	N		
Sample Number	-	VCP441767	 	
Sample Date		28 Sep 2023	 	
Machine Hours		7035	 	
Oil Hours		0	 	
Oil Changed		Not Changd	 	
Sample Status		ABNORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>194</b>	 	
VOLVO				
CONTAI	MOITAMIN			
Silicon	ppm	<b>40</b>	 	
Sodium	ppm	<b>■</b> 3	 	
Potassium	ppm	<b>2</b>	 	
WEAR N	AFTAI S			
_		<u>▲</u> 553	 	
Iron	ppm	<u>8</u>	 	
Copper Lead	ppm	<b>■</b> 5	 	
Tin	ppm	<u> </u>	 	
Aluminum	ppm	<b>□</b> <1	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	<b>0</b>	 	
Nickel	ppm	0	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	<b>■</b> 9	 	
Vanadium	ppm	0	 	
variadium	ppiii	V		
VOLVO				
ADDITIV	/EZ			
Calcium	ppm	■3967	 	
Magnesium	ppm	<b>11</b>	 	
Zinc	ppm	<b>2278</b>	 	
Phosphorus	ppm	■1377	 	
Barium	ppm	<b>■</b> 3	 	
Boron	ppm	<b>115</b>	 	



ALTA EQUIPMENT CO - ORLAND PARK 5000 INDUSTRIAL HWY GARY, IN US 46406 Contact: DAVE ENG DAVE.ENG@ALTG.COM T: (312)350-2560 F:

## Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor. Gear wear is indicated. All other component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO8885Unique No:10673251Signed:Don BaldridgeReport Date:04 Oct 2023



## **CONSTRUCTION EQUIPMENT**





