



CONSTRUCTION EQUIPMENT

24106 VOLVO A45G 352521 - TRANSMISSION (AUTO)



Sample No: VCP433894
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 24106



218 - ASCENDUM MACHINERY INC - N. CHARLESTON
 7235 CROSS COUNTRY RD.
 NORTH CHARLESTON, SC
 US 29418
 Contact: MATT MITCHAM
 matt.mitcam@ascendummachinery.com
 T:
 F: (843)414-1129



SAMPLE INFORMATION

Sample Number	VCP433894	---	---	---
Sample Date	25 Sep 2023	---	---	---
Machine Hours	6453	---	---	---
Oil Hours	2000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 26.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 0	---	---	---



WEAR METALS

Iron	ppm	█ 48	---	---	---
Copper	ppm	█ 76	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 8	---	---	---
Aluminum	ppm	█ 18	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 12	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	35	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 177	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 75	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO3387
Unique No: 10673288
Signed: Don Baldrige
Report Date: 04 Oct 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

