



CONSTRUCTION EQUIPMENT

VOLVO A25G 752580 - TRANSMISSION (AUTO)



Sample No: VCP441065
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No:



ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: BRAD BYRO
 bradley.byro@altg.com
 T:
 F: (407)659-8720



SAMPLE INFORMATION

Sample Number	VCP441065	---	---	---
Sample Date	26 Sep 2023	---	---	---
Machine Hours	614	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 29.5	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 3	---	---	---
Potassium	ppm	█ 3	---	---	---



WEAR METALS

Iron	ppm	█ 16	---	---	---
Copper	ppm	█ 12	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 2	---	---	---
Aluminum	ppm	█ 10	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	< 1	---	---	---



ADDITIVES

Calcium	ppm	█ 69	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 198	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 94	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0096
Unique No: 10674637
Signed: Wes Davis
Report Date: 04 Oct 2023



CONSTRUCTION EQUIPMENT



GRAPHS

