

CONSTRUCTION EQUIPMENT
RASON SENNEBOGEN 875 875.5.1071 - REAR RIGHT FINAL DRIVE

Sample No: VCP407785

Oil Type: **NOVESTAR 80W90**

Job No: **RASON**

VOLVO					
SAMPLE INFORMATION					
Sample Number	-	VCP407785			
Sample Date		13 Sep 2023			
Machine Hours		2036			
Oil Hours		1000			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	199			
VOLVO					
CONTAM	INATION				
Silicon	ppm	■ 3			
Sodium	ppm	2			
Potassium	ppm	1			
WEAR METALS					
Iron	ppm	■90			
Copper	ppm	13			
Lead	ppm	■<1			
Tin	ppm	■<1			
Aluminum	ppm	■3			
Chromium	ppm	■<1			
Molybdenum	ppm	0			
Nickel	ppm	■<1			
Titanium	ppm	0			
Silver	ppm	0			
Manganese	ppm	3			
Vanadium	ppm	0			
VOLVO					
ADDITIV	Z				
Calcium	ppm	5			
Magnesium	ppm	0			
Zinc	ppm	0			
Phosphorus	ppm	716			
Barium	ppm	0			
Boron	ppm	27			



GREEN MACHINE SERVICES LLC

13 SPYROS DRIVE SOUTH AMBOY, NJ US 08879 Contact: JOE GRZANKOWSKI JOE@GREENMSRV.COM T: (732)673-5920 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **GRESOUNJ Unique No:** 10675836 Signed: Wes Davis Report Date: 05 Oct 2023



CONSTRUCTION EQUIPMENT





