

# **CONSTRUCTION EQUIPMENT**SENNEBOGEN 875 875.5.1071 - REAR LEFT FINAL DRIVE



Sample No: VCP407671

Oil Type: NAVESTAR 80W90

Job No:

CAMDIE	INFORMATIO	<b>Y</b>		
	INFURMATIUI		<u>.</u>	
Sample Number		VCP407671	 	
Sample Date		13 Sep 2023	 	
Machine Hours		2036	 	
Oil Hours		1000	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>112</b>	 	
VI3C @ 40 C	CSt			
VOLVO				
CONTAN	MINATION			
Silicon	ppm	<b>2</b>	 	
Sodium	ppm	<b>■2</b>	 	
Potassium	ppm	<b>■&lt;1</b>	 	
WEAR	AETAL C			
WEAK	IL I ALS	<u>.</u>	<u>.</u>	
Iron	ppm	■ 57	 	
Copper	ppm	<b>16</b>	 	
Lead	ppm	<b>■</b> <1	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	■4	 	
Chromium	ppm	<b>■</b> <1	 	
Molybdenum	ppm	2	 	
Nickel	ppm	<b>■</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
ADDITIV	/ES			
Calcium	ppm	361	 	
Magnesium	ppm	0	 	
Zinc	ppm	197	 	
Phosphorus	ppm	613	 	
Barium	ppm	0	 	
Boron	ppm	22	 	



#### **GREEN MACHINE SERVICES LLC**

13 SPYROS DRIVE SOUTH AMBOY, NJ US 08879 Contact: JOE GRZANKOWSKI JOE@GREENMSRV.COM T: (732)673-5920 F:

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:GRESOUNJUnique No:10675901Signed:Wes DavisReport Date:05 Oct 2023



## **CONSTRUCTION EQUIPMENT**





