

## CONSTRUCTION EQUIPMENT D12844 WE ENERGIES VOLVO L220H 3482 - REAR AXLE

Sample No: VCP414075 Oil Type: VOLVO WB 102

Job No: D12844 WE ENERGIES

SAMPLE	INFORMATIO	N		
Sample Number		VCP414075	VCP418970	 
Sample Date		27 Sep 2023	28 Jul 2023	 
Machine Hours		947	582	 
Oil Hours		947	582	 
Oil Changed		Changed	Not Changd	 
Sample Status		NORMAL	ABNORMAL	 
Sample Status		NORWAL	ADNORIVIAL	 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>41.2</b>	<b>41.5</b>	 
VOLVO				
VOLVO	MINATION			
Silicon	ppm	<b>9</b>	<b>1</b> 0	 
Sodium	ppm	<b>2</b>	<b>3</b>	 
Potassium	ppm	<b>■&lt;1</b>	< 1	 
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>19</b>	<b>2</b> 2	 
Copper	ppm	<b>■&lt;1</b>	1	 
Lead	ppm	■0	<b></b> <1	 
Tin	ppm	■0	0	 
Aluminum	ppm	<b>-&lt;1</b>	<b>3</b>	 
Chromium	ppm	<b>■&lt;1</b>	<b>-</b> <1	 
Molybdenum	ppm	<b></b>	<b>3</b>	 
Nickel	ppm	■0	0	 
Titanium	ppm	0	<1	 
Silver	ppm	0	0	 
Manganese	ppm	■3	■3	 
Vanadium	ppm	0	<1	 
ADDITIV	/ES			
Calcium	ppm	■3830	■3850	 
Magnesium	ppm	<b>12</b>	<b>1</b> 3	 
Zinc	ppm	<b>1627</b>	<b>1551</b>	 
Phosphorus	ppm	<b>1312</b>	<b>1282</b>	 
Barium	ppm	<b>■</b> 0	<b>0</b>	 
Boron	ppm	<b>121</b>	<b>137</b>	 



ARING EQUIPMENT COMPANY INC - MAIN (MILWAUKEE) 13001 W SILVERE SPRING DR BUTLER, WI US 53007 Contact: GLENN OTTENBACHER gottenbacher@aring.com T: (262)282-0715 F: (262)781-5053

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0069 **Unique No:** 10682504 Signed: Wes Davis Report Date: 06 Oct 2023



## **CONSTRUCTION EQUIPMENT**





