

CONSTRUCTION EQUIPMENT VOLVO A60H 350157 - DIESEL FUEL



Sample No:VCP433233Oil Type:NOT GIVEN

Job No:

	E INFORMATION			
Sample Number		VCP433233	 	
Sample Date		05 Oct 2023	 	 M
Machine Hours		0	 	 PO
Sample Status		NORMAL	 	 SP
				US
VOLVO				Co
	ONDITION			ms
Sulfur	ppm	0	 	 T: (
Visc @ 40°C	cSt	2.4	 	 F:
VOLVO	MINATION			
	MINATION			Di
Water	%	0.004	 	 N
Lead	ppm	 <1	 	 at
Nickel	ppm	0	 	 nc
Aluminum	ppm	0	 	 sy
Vanadium	ppm	0	 	 ne
Silicon	ppm	0	 	 ar

MORGAN CORP

PO BOX 3555 SPARTANBURG, SC US 29304 Contact: MICHAEL SHEPARD mshepard@morgan-corp.com T: (864)433-8800 r.

Diagnosis

No corrective action is recommended at this time.All metal levels are normal indicating no corrosion in the system. The water content is negligible. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

Depot:MORSPAUnique No:10683824Signed:Doug BogartReport Date:15 Oct 2023



VOLVO

GRAPHS



Pensky-Martens Flash Point (°C)

					empe	erature	د				
	-10	-8	-6	-4	-2	0	2	4	6	8	10
	L	ł	ł	ļ	ļ	ļ	ļ	ļ	ļ	Ī	_
0rt5/23.	4			-			į	j		1	
00000											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
											_
0.4E/22	_		1								
UCLU/EN											