

# CONSTRUCTION EQUIPMENT ASCENDUM MACHINERY VOLVO A60H 480007 (S/N 340109) - DIESEL

Sample No: VCP433234 **Oil Type:** NOT GIVEN

### Job No:

SAMPL	E INFORMATION	l	 	
Sample Number	- -	VCP433234	 	
Sample Date		05 Oct 2023	 	
Machine Hours		0	 	
Sample Status		NORMAL	 	
FUEL C	ONDITION			
Sulfur	ppm	0	 	
Visc @ 40°C	cSt	2.42	 	
CONTA	MINATION			
Water	%	0.003	 	
_ead	ppm	0	 	
Nickel	ppm	0	 	
Aluminum	ppm	0	 	
Vanadium	ppm	0	 	
Silicon	ppm	0	 	

#### IORGAN CORP

O BOX 3555 PARTANBURG, SC S 29304 ontact: MICHAEL SHEPARD shepard@morgan-corp.com (864)433-8800

## Diagnosis

No corrective action is recommended at this time.All metal levels are normal indicating no corrosion in the ystem. The water content is negligible. There is no indication of any contamination in the fuel. The condition of the fuel is acceptable for the time in service.

Depot: MORSPA Unique No: 10683825 Signed: Doug Bogart Report Date: 15 Oct 2023



VOLVO

GRAPHS



## Pensky-Martens Flash Point (°C)

					nciiin	amperature	د				
	10	-8	-6	-4	-2	0	2	4	6	8	10
001.0		ŀ	ļ	Ļ	ļ	ļ.	ļ,	ļ	ļ	ļ.	τ.
Uct5/23	Ļ			1			İ.	i		i.	-
0ct5/23	1			1	Ì		Ì	i		1	