



# CONSTRUCTION EQUIPMENT

SPM594618 ALPINE DEM VOLVO EC750E 314070 - RIGHT SWING DRIVE



**Sample No:** VCP415205  
**Oil Type:** GEAR OIL SAE 80W90  
**Job No:** SPM594618 ALPINE DEM



**ALTA EQUIPMENT CO - ORLAND PARK**  
 5000 INDUSTRIAL HWY  
 GARY, IN  
 US 46406  
 Contact: DAVE ENG  
 DAVE.ENG@ALTG.COM  
 T: (312)350-2560  
 F:



## SAMPLE INFORMATION

Sample Number	VCP415205	---	---	---
Sample Date	28 Sep 2023	---	---	---
Machine Hours	1522	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	█ 168	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Water	%	NEG	---	---	---
Silicon	ppm	█ 12	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 2	---	---	---



## WEAR METALS

Iron	ppm	█ 209	---	---	---
Copper	ppm	█ 13	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 32	---	---	---
Magnesium	ppm	█ <1	---	---	---
Zinc	ppm	█ 25	---	---	---
Phosphorus	ppm	█ 285	---	---	---
Barium	ppm	█ 7	---	---	---
Boron	ppm	█ 0	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO8885  
**Unique No:** 10686316  
**Signed:** Don Baldrige  
**Report Date:** 12 Oct 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

