



CONSTRUCTION EQUIPMENT

SW1024614 ODDONETTO VOLVO EC750E 314229 - REAR RIGHT FINAL DRIVE



Sample No: VCP415383
Oil Type: GEAR OIL SAE 80W90
Job No: SW1024614 ODDONETTO



ARNOLD MACHINERY COMPANY
 4323 EAST WINSLOW AVENUE
 PHOENIX, AZ
 US 85040
 Contact: RANDY PRZEKURAT
 randyp@arnoldmachinery.com
 T:
 F: (602)414-1904



SAMPLE INFORMATION

Sample Number	VCP415383	---	---	---
Sample Date	01 Oct 2023	---	---	---
Machine Hours	544	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 173	---	---	---
-------------	-----	-------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 10	---	---	---
Sodium	ppm	█ 2	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 328	---	---	---
Copper	ppm	█ 1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	<1	---	---	---



ADDITIVES

Calcium	ppm	█ 14	---	---	---
Magnesium	ppm	█ 1	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 347	---	---	---
Barium	ppm	█ 10	---	---	---
Boron	ppm	█ 0	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO6174
Unique No: 10686369
Signed: Don Baldrige
Report Date: 12 Oct 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

