



# CONSTRUCTION EQUIPMENT

## VOLVO A25G 742124 - COOLANT



**Sample No:** VCP433755  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:**



### SAMPLE INFORMATION

Sample Number	VCP433755	---	---	---
Sample Date	09 Oct 2023	---	---	---
Machine Hours	7655	---	---	---
Sample Status	NORMAL	---	---	---



### COOLANT CONDITION

pH	Scale 0-14	■ 7.19	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 0	---	---	---
Percentage Glycol	%	■ 44.6	---	---	---
Freezing Point	°C	■ -21	---	---	---



### CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**ALTA EQUIPMENT COMPANY**  
 5151 DR MARTIN LUTHER KING BLVD  
 FORT MYERS, FL  
 US 33905  
 Contact: TODD LARK  
 tlark@altaequipfl.com  
 T:  
 F: (239)481-3302

### Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** VOLVO0090  
**Unique No:** 10687238  
**Signed:** Doug Bogart  
**Report Date:** 16 Oct 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

