

CONSTRUCTION EQUIPMENT

607580 SENNEBOGEN 840 2345 - FRONT LEFT FINAL DRIVE

Sample No: VCP431506

Oil Type: VOLVO PREMIUM GEAR OIL 80W-90 GL-5

Job No: 607580

CUMDIE	INFORMATION				
	INI UNIIA I IUN				_
Sample Number		VCP431506	VCP421771		
Sample Date		11 Oct 2023	03 Apr 2023		
Machine Hours		2072	1029		
Oil Hours		0	1029		
Oil Changed		Changed	Changed		
Sample Status		NORMAL	NORMAL		
VOLVO					
OIL CONDITION					
Visc @ 40°C	cSt	154	□ 187		
VISC @ 40 C	CSt	134	107		
VOLVO					
CONTAMI	NATION				
Silicon	ppm	3	1		
Sodium	ppm	■ 3	2		
Potassium	ppm	0	0		
WEAR METALS					
WEAR MI	FIAL2				
Iron	ppm	■36	□ 44		
Copper	ppm	■8	■8		
Lead	ppm	■0	0		
Tin	ppm	0	0		
Aluminum	ppm	■ <1	1		
Chromium	ppm	■ 0	0		
Molybdenum	ppm	■ 0	0		
Nickel	ppm	0	0		
Titanium	ppm	0	0		
Silver	ppm	0	0		
Manganese	ppm	2	2		
Vanadium	ppm	0	0		
ADDITIVI	2				
Calcium	ppm	■ 9	1 4		
Magnesium	ppm	13	_2		
Zinc	ppm	0	< 1		
Phosphorus	ppm	1416	■1024		
Barium	ppm	161	■318		
Boron	ppm	115	0		



FERROUS PROCESSING AND TRADING

3400 E LAFAYETTE DETROIT, MI US 48207 Contact: KEITH HALL keith.hall@fpt1.com T:

Diagnosis

F:

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:FERDETUnique No:10698734Signed:Don BaldridgeReport Date:19 Oct 2023

Contact/Location: KEITH HALL - FERDET



CONSTRUCTION EQUIPMENT





