



CONSTRUCTION EQUIPMENT

SWO-066610 VOLVO A60H 340099 - COOLANT



Sample No: VCP429587
Oil Type: VOLVO COOLANT VCS (YELLOW)
Job No: SWO-066610



SAMPLE INFORMATION

Sample Number	VCP429587	VCP370869	VCP366754	VCP362826
Sample Date	11 Oct 2023	14 Oct 2022	26 Jul 2022	03 May 2022
Machine Hours	7982	6595	6024	5500
Sample Status	NORMAL	NORMAL	ABNORMAL	NORMAL

SAIIA CONSTRUCTION LLC

4400 LEWISBURG RD
 BIRMINGHAM, AL
 US 35207

Contact: STEPHANI BRITTON
 sbritton@saiia.com;doug.bogart@wearcheck.com
 T: (205)943-2268
 F: (205)943-2269



COOLANT CONDITION

pH	Scale 0-14	7.84	8.20	8.51	8.84
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	NT	0	0	636
Percentage Glycol	%	51.2	49.9	49.8	49.8
Freezing Point	°C	-38	-33	-33	-33

Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.



CONTAMINATION

Coolant Appearance	normal	normal	▲ sediment	normal
Coolant Color	Yllow	Yllow	Yllow	Yllow

Depot: SAIBIR
Unique No: 10698960
Signed: Jonathan Hester
Report Date: 24 Oct 2023




CONSTRUCTION EQUIPMENT




GRAPHS


Iron/Tin/Silver




Reserve Alkalinity




Copper/Aluminum/Lead



Freeze Point



pH



Nitrites

