



# CONSTRUCTION EQUIPMENT

369350 SENNEBOGEN 835 835.0.2487 - REAR AXLE



**Sample No:** VCP396384  
**Oil Type:** VOLVO PREMIUM GEAR OIL 80W-90 GL-5  
**Job No:** 369350



## SAMPLE INFORMATION

Sample Number	VCP396384	---	---	---
Sample Date	09 Oct 2023	---	---	---
Machine Hours	11163	---	---	---
Oil Hours	2000	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

### ALTA EQUIPMENT COMPANY

1035 WYLIE DRIVE  
 BLOOMINGTON, IL  
 US 61705

Contact: JUSTIN PERRY  
 justin.perry@altg.com  
 T: (309)533-9285  
 F:



## OIL CONDITION

Visc @ 40°C	cSt	█ 149	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 0	---	---	---



## WEAR METALS

Iron	ppm	█ 21	---	---	---
Copper	ppm	█ 28	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 21	---	---	---
Magnesium	ppm	█ 11	---	---	---
Zinc	ppm	█ 31	---	---	---
Phosphorus	ppm	1991	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 120	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO5054  
**Unique No:** 10699934  
**Signed:** Wes Davis  
**Report Date:** 19 Oct 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

