
## CONSTRUCTION EQUIPMENT WETHERING TRACTOR VOLVO A25G 752113 - TRANSMISSION

Sample No:VCP435790Oil Type:DIESEL ENGINE OIL SAE 15W40Job No:WETHERING TRACTOR

JOD NO:

VOLVO

## SAMPLE INFORMATION Sample Number VCP435790 VCP360682 Sample Date 05 Oct 2023 09 Apr 2022 Machine Hours 2686 1636 Oil Hours 0 1636 Oil Changed N/A Not Changd NORMAL NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 29.6 30.3 CONTAMINATION Water % NEG NEG 12 Silicon 14 ppm Sodium 8 7 ppm Potassium ppm 2 0 WEAR METALS 44 Iron ppm 32 Copper ppm 51 41 Lead ppm 0 🔲 0 Tin ppm 10 7 Aluminum 34 28 ppm



01 **ADDITIVES** Calcium 163 167 ppm 0 Magnesium 4 ppm Zinc ppm 8 4 Phosphorus 263 259 ppm Barium 2 0 ppm Boron 83 86 ppm



**RIPA AND ASSOCIATES** 

10149 FISHER AVENUE TAMPA, FL US 33619 Contact: PM Services PMServices@ripaconstruction.com T: F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.


Depot:RIPTAMUnique No:10699948Signed:Sean FeltonReport Date:19 Oct 2023Contact/Location: PM Services ? - RIPTAM

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: RIPTAM [WUSCAR] 05982653 (Generated: 05/21/2024 11:52:23) Rev: 1

Contact/Location: PM Services ? - RIPTAM Page 2 of 2