CONSTRUCTION EQUIPMENT ATLAS ORGANICS VOLVO EC220EL 314414 - HYDRAULIC SYSTEM

Sample No:VCP442744Oil Type:NOT GIVENJob No:ATLAS ORGANICS

Chromium

Nickel

Silver

Titanium

Manganese

Vanadium

Molybdenum

VOLVO

VOLVO				
	FORMATION			
Sample Number	-	VCP442744	 	
Sample Date		27 Sep 2023	 	
Machine Hours		2019	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CONDI	TION			
Visc @ 40°C	cSt	41.8	 	
Acid Number (AN)	mg KOH/g	0.53	 	
CONTAMIN	NATION			
Particles >4µm	-	22329	 	
Particles >6µm		3456	 	
Particles >14µm		162	 	
ISO 4406:1999 (c)		22/19/15	 	
Silicon	ppm	5	 	
Sodium	ppm	∎1	 	
Potassium	ppm	0	 	
WEAR ME	TALS			
Iron	ppm	4	 	
Copper	ppm	26	 	
Lead	ppm	0	 	
Tin	ppm	0	 	
Aluminum	ppm	0	 	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619

Contact: KENNY HANEY khaney@flaglerce.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is SAE 10W AW Hydraulic Oil. Please confirm the oil type and grade, and specify the brand of the oil on your next sample.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Calcium	ppm	72	 	
Magnesium	ppm	0	 	
Zinc	ppm	455	 	
Phosphorus	ppm	364	 	
Barium	ppm	0	 	
Boron	ppm	0	 	

 Depot:
 VOLV0093

 Unique No:
 10700839

 Signed:
 Wes Davis

 Report Date:
 25 Oct 2023

|| <1

0

0

0

0

0

0

ppm

ppm

ppm

ppm

ppm

ppm

ppm


ADDITIVES

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 05983544 (Generated: 10/27/2023 01:35:50) Rev: 1

Contact/Location: KENNY HANEY - VOLVO0093