

## CONSTRUCTION EQUIPMENT 19708 STRATEGIC MAT VOLVO L90H 625283 - REAR AXLE

Sample No: VCP435270 Oil Type: VOLVO WB 102

Job No: 19708 STRATEGIC MAT

VOLVO SAMPLE	INFORMATIO	N		
Sample Number	. IMI OMPIN I IOI	VCP435270	VCP335844	 
Sample Number				
Machine Hours		26 Sep 2023 3029	15 Sep 2021 1040	 
Oil Hours		0	0	
Oil Changed		Not Changd	Changed	 
Sample Status		NORMAL	NORMAL	 
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	<b>43.2</b>	<b>1</b> 40.2	 
VOLVO	anis Tioni			
LUNIAN	MINATION			
Silicon	ppm	<b>14</b>	<b>1</b> 3	 
Sodium	ppm	<b>0</b>	■8	 
Potassium	ppm	<b>■</b> 3	□ 0	 
WEAR	METALS			
Iron	ppm	<b>41</b>	<b>6</b> 6	 
Copper	ppm	<b>4</b>	<b>28</b>	 
Lead	ppm	<b>■&lt;1</b>	<b>0</b>	 
Tin	ppm	<b></b>	1	 
Aluminum	ppm	<b>2</b>	< 1	 
Chromium	ppm	<b>■&lt;1</b>	<b>3</b>	 
Molybdenum	ppm	<b>2</b>	2	 
Nickel	ppm	<b>■&lt;1</b>	0	 
Titanium	ppm	<1	0	 
Silver	ppm	0	<1	 
Manganese	ppm	<b>2</b>	8	 
Vanadium	ppm	0	0	 
ADDITIV	/ES			
Calcium	ppm	<b>4349</b>	3719	 
Magnesium	ppm	<b>25</b>	10	 
Zinc	ppm	<b>1758</b>	1447	 
Phosphorus	ppm	<b>1373</b>	1192	 
Barium	ppm	<b>■&lt;1</b>	0	 
Boron	ppm	<b>142</b>	172	 
	1.1.	_		



117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST

GREENVILLE, NC US 27834

Contact: BRANDON JENKINS BRANDON, JENKINS@ASCENDUMMACHINERY.COM

T:

F: (704)494-8197

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO8769 **Unique No:** 10702478 Signed: Wes Davis Report Date: 23 Oct 2023



## **CONSTRUCTION EQUIPMENT**





