



# CONSTRUCTION EQUIPMENT

19772 LANE-BLYTHE VOLVO A45GFS 352252 - COOLANT



**Sample No:** VCP441297  
**Oil Type:** NOT GIVEN  
**Job No:** 19772 LANE-BLYTHE



## SAMPLE INFORMATION

Sample Number	VCP441297	---	---	---
Sample Date	05 Oct 2023	---	---	---
Machine Hours	6445	---	---	---
Sample Status	ABNORMAL	---	---	---



## COOLANT CONDITION

pH	Scale 0-14	■ 7.46	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ 676	---	---	---
Percentage Glycol	%	■ 41.9	---	---	---
Freezing Point	°C	■ -15	---	---	---



## CONTAMINATION

Coolant Appearance	▲ sediment	---	---	---
Coolant Color	Red	---	---	---



117 - ASCENDUM MACHINERY INC - GREENVILLE  
2002 N GREENE ST  
GREENVILLE, NC  
US 27834  
Contact: BRANDON JENKINS  
BRANDON.JENKINS@ASCENDUMMACHINERY.COM  
T:  
F: (704)494-8197

## Diagnosis

We recommend drain/flush system, and refill with 50/50 antifreeze water mixture. Sediment present. Carboxylate test failed. Glycol and nitrite levels are acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** VOLVO8769  
**Unique No:** 10702578  
**Signed:** Doug Bogart  
**Report Date:** 24 Oct 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

