

## CONSTRUCTION EQUIPMENT 19708 STRATEGIC MAT VOLVO L90H 625283 - COOLANT

Sample No: VCP435276

Oil Type: **VOLVO COOLANT VCS (YELLOW)** 

Job No: 19708 STRATEGIC MAT

SAMPLE II	NFORMATION				
Sample Number		VCP435276			
Sample Date		26 Sep 2023			
Machine Hours		3029			
Sample Status		NORMAL			
COOLANT CONDITION					
COULANT CONDITION					
рН	Scale 0-14	<b>7.44</b>			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	<b>0</b>			
Percentage Glycol	%	<b>■</b> 50.5			
Freezing Point	°C	<b>-35</b>			
VOLVO	IATION				
CONTAMIN	TATIUN				
Coolant Appearance		normal			
Coolant Color		Yllow			



117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST

GREENVILLE, NC US 27834

> Contact: BRANDON JENKINS BRANDON, JENKINS@ASCENDUMMACHINERY.COM

F: (704)494-8197

## Diagnosis

The fluid is suitable for further service. There is no indication of any contamination in the coolant. The carboxylate level of this fluid is acceptable. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO8769 **Unique No:** 10702579 Signed: Doug Bogart Report Date: 24 Oct 2023



## **CONSTRUCTION EQUIPMENT**





## GRAPHS

