

CONSTRUCTION EQUIPMENT 19698 SRM CONCRETE VOLVO L70H 623293 - COOLANT



Oil Type: **VOLVO COOLANT VCS (YELLOW)**

Job No: 19698 SRM CONCRETE

SAMPLE II	NFORMATION				
Sample Number		VCP414137			
Sample Date		25 Sep 2023			
Machine Hours		3042			
Sample Status		NORMAL			
COOLANT CONDITION					
COULANT CONDITION					
рН	Scale 0-14	7.80			
Reserve Alkalinity	Scale 0-20				
Nitrites	ppm	0			
Percentage Glycol	%	■ 50.8			
Freezing Point	°C	-35			
VOLVO	IATION				
CONTAMIN	MATIUN	_			
Coolant Appearance		normal			
Coolant Color		Yllow			



117 - ASCENDUM MACHINERY INC - GREENVILLE 2002 N GREENE ST

GREENVILLE, NC US 27834

> Contact: BRANDON JENKINS BRANDON, JENKINS@ASCENDUMMACHINERY.COM

F: (704)494-8197

Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

Depot: VOLVO8769 **Unique No:** 10702580 Signed: Doug Bogart Report Date: 24 Oct 2023



CONSTRUCTION EQUIPMENT





GRAPHS

