CONSTRUCTION EQUIPMENT X47832 VOLVO A25G 752432 - DIESEL ENGINE



Sample No:VCP432536Oil Type:DIESEL ENGINE OIL SAE 15W40

Job No: X47832

VOLVO

SAMPLE INFORMATION VCP432536 Sample Number Sample Date 16 Oct 2023 Machine Hours 2111 Oil Hours 0 Oil Changed N/A ABNORMAL Sample Status **OIL CONDITION** Visc @ 100°C cSt 13.0 Base Number (BN) mg KOH/g 6.4 Oxidation (PA) 87 % CONTAMINATION % 0.7 Soot % Nitration (PA) % 85 Sulfation (PA) % 64 % NEG Glycol Fuel % <1.0 Silicon ppm 11 Sodium ppm 3



SCOTT EQUIPMENT COMPANY LLC - Lake Charles PO BOX 16955 LAKE CHARLES, LA US 70616 Contact: TINA LEDOUX tledoux@scottcompanies.com T: (337)433-9811 F: (318)433-6623

Diagnosis

No corrective action is recommended at this time. Resample at the next service interval to monitor.The copper level is abnormal. All other component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Potassium

ppm

3

VOLVO				
WEAR I	METALS			
Iron	ppm	27	 	
Copper	ppm	<u> </u>	 	
Lead	ppm	1	 	
Tin	ppm	2	 	
Aluminum	ppm	4	 	
Chromium	ppm	1	 	
Molybdenum	ppm	45	 	
Nickel	ppm	5	 	
Titanium	ppm	 <1	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	<1	 	

Vanadia

ADDITIVES								
Calcium	ppm	1836						
Magnesium	ppm	461						
Zinc	ppm	1169						
Phosphorus	ppm	854						
Barium	ppm	0						
Boron	ppm	1 3						

 Depot:
 VOLVO6244

 Unique No:
 10702592

 Signed:
 Don Baldridge

 Report Date:
 24 Oct 2023

Report Id: VOLVO6244 [WUSCAR] 05985297 (Generated: 10/24/2023 14:36:38) Rev: 1


Contact/Location: TINA LEDOUX - VOLVO6244

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Contact/Location: TINA LEDOUX - VOLVO6244