
CONSTRUCTION EQUIPMENT 607627 MOSAIC VOLVO EC480EL 315030 - HYDRAULIC SYSTEM

Sample No:VCP426239Oil Type:VOLVO SUPER HYDRAULIC OIL 46Job No:607627 MOSAIC

SAMPLE INFORMATION

VOLVO

Sample Number		VCP426239						
Sample Date		29 Sep 2023						
Machine Hours		584						
Oil Hours		584						
Oil Changed		Not Changd						
Sample Status		ATTENTION						
OIL CONDITION								
Visc @ 40°C	cSt	42.4						
Acid Number (AN)	mg KOH/g	0.51						
CONTAMINATION								
Domiclos > 1,000		A 40170						



WEAR METALS

Iron	ppm	0	 	
Copper	ppm	1 3	 	
Lead	ppm	1	 	
Tin	ppm	□ <1	 	
Aluminum	ppm	 <1	 	
Chromium	ppm	0	 	
Molybdenum	ppm	0	 	
Nickel	ppm	□ <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	 <1	 	
Vanadium	ppm	0	 	

Calcium	ppm	92				
Magnesium	ppm	4				
Zinc	ppm	605				
Phosphorus	ppm	439				
Barium	ppm	0				
Boron	ppm	0				



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

Diagnosis

The filter change at the time of sampling has been noted. Resample at the next service interval to monitor.All component wear rates are normal. There is a light amount of silt (particulates < 14 microns in size) present in the oil. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

 Depot:
 VOLVO0033

 Unique No:
 10709063

 Signed:
 Wes Davis


 Report Date:
 24 Oct 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 05986401 (Generated: 10/25/2023 10:50:26) Rev: 1

Contact/Location: JOHN FARDELLA - VOLVO0093