

CONSTRUCTION EQUIPMENT
375637 WEINTRAB RECY VOLVO EC300 310153 - HYDRAULIC SY

Sample No: VCP414648

Sodium

Potassium

Oil Type: **VOLVO SUPER HYDRAULIC OIL 46**

Job No: 375637 WEINTRAB RECY

ppm

ppm

2

SAMPLE IN	NFORMATION			
Sample Number	-	VCP414648	VCP377789	
Sample Date		04 Oct 2023	01 Aug 2022	
Machine Hours		5303	3343	
Oil Hours		2300	1500	
Oil Changed		Changed	Not Changd	
Sample Status		NORMAL	NORMAL	
OIT CONDI.	TION			
Visc @ 40°C	cSt	■39.0	46.5	
Acid Number (AN)	mg KOH/g	■ 0.27	□ 0.43	
CONTAMIN	IATION			
Particles >4µm		11634	■30224	
Particles >6µm		■948	1413	
Particles > 14µm		47	■ 35	
ISO 4406:1999 (c)		21/17/13	22/18/12	
Silicon	ppm	■ 9	1 2	

WEAR	METALS			
Iron	ppm	12	■8	
Copper	ppm	■23	■36	
Lead	ppm	1	1	
Tin	ppm	■<1	<1	
Aluminum	ppm	2	2	
Chromium	ppm	■2	- <1	
Molybdenum	ppm	■<1	2	
Nickel	ppm	■<1	0	
Titanium	ppm	0	0	
Silver	ppm	0	<1	
Manganese	ppm	■<1	0	
Vanadium	ppm	0	0	

- < 1

ADDIT	IVES			
Calcium	ppm	100	1 31	
Magnesium	ppm	10	1 0	
Zinc	ppm	463	503	
Phosphorus	ppm	■355	■391	
Barium	ppm	0	0	
Boron	ppm	■ 0	4	



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC 8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. The system cleanliness is acceptable for your target ISO 4406 cleanliness code. The system and fluid cleanliness is acceptable. The AN level is acceptable for this fluid. The condition of the oil is suitable for further service.

Depot: VOLVO0093 **Unique No:** 10709073 Signed: Wes Davis Report Date: 24 Oct 2023



CONSTRUCTION EQUIPMENT





GRAPHS

