



CONSTRUCTION EQUIPMENT

VOLVO L70H 624659 - REAR AXLE



Sample No: VCP433523
Oil Type: VOLVO WET BRAKE TRANSAXLE OIL
Job No:



SAMPLE INFORMATION

Sample Number	VCP433523	---	---	---
Sample Date	19 Oct 2023	---	---	---
Machine Hours	2477	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT COMPANY
 5151 DR MARTIN LUTHER KING BLVD
 FORT MYERS, FL
 US 33905
 Contact: TODD LARK
 tlark@altaequipfl.com
 T:
 F: (239)481-3302



OIL CONDITION

Visc @ 40°C	cSt	█ 43.0	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 18	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 4	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 86	---	---	---
Copper	ppm	█ 37	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 3	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ 3	---	---	---
Molybdenum	ppm	█ 3	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 9	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 3750	---	---	---
Magnesium	ppm	█ 10	---	---	---
Zinc	ppm	█ 1628	---	---	---
Phosphorus	ppm	█ 1397	---	---	---
Barium	ppm	█ 9	---	---	---
Boron	ppm	█ 127	---	---	---

Depot: VOLVO0090
Unique No: 10709604
Signed: Wes Davis
Report Date: 24 Oct 2023



CONSTRUCTION EQUIPMENT



GRAPHS

