

CONSTRUCTION EQUIPMENT 24151 VOLVO L350 1222 - REAR AXLE



Sample No: VCP435070 **Oil Type:** VOLVO WB 102

Job No: 24151

VOLVO	INFORMATIO	1		
	INFURMATIU		_	
Sample Number		VCP435070	VCP407135	
Sample Date		18 Oct 2023	24 May 2023	
Machine Hours		4423	1980	
Oil Hours		0	1100	
Oil Changed		Changed	Changed	
Sample Status		NORMAL	NORMAL	
VOLVO				
OIL CON	DITION			
Visc @ 40°C	cSt	44.8	□ 52.3	
VOLVO				
CONTAN	MOITANIN			
Silicon	ppm	9	1 4	
Sodium	ppm	■ 0	0	
Potassium	ppm	2	2	
WEAR N	AETAL C			
_	JE I ALS			
ron	ppm	66	□206	
Copper	ppm	■8	7	
Lead	ppm		< 1	
Tin	ppm	■ <1	<u></u> <1	
Aluminum	ppm	■2	< 1	
Chromium	ppm	■<1	1	
Molybdenum	ppm	■3	1	
Vickel	ppm	0	0	
Titanium	ppm	0	<1	
Silver	ppm	0	0	
Manganese	ppm	-<1	□3	
/anadium	ppm	0	0	
ADDITIV	/ES			
Calcium	-	3105	□ 3484	
Magnesium	ppm	16	7	
Zinc	ppm	■ 1429	1463	
	ppm			
Phosphorus	ppm	1235	1191	
Barium	ppm	0	0	
Boron	ppm	107	1 02	



218 - ASCENDUM MACHINERY INC - N. CHARLESTON 7235 CROSS COUNTRY RD. NORTH CHARLESTON, SC US 29418 Contact: MATT MITCHAM matt.mitcham@ascendummachinery.com T: F: (843)414-1129

. .

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO3387Unique No:10709632Signed:Wes DavisReport Date:24 Oct 2023



CONSTRUCTION EQUIPMENT





