## **CONSTRUCTION EQUIPMENT** 607581 PRIMERIS

VOLVO A40G 352384 - TRANSMISSION (AUTO

Sample No: VCP424418

VOLVO

**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102 Job No: 607581 PRIMERIS

## SAMPLE INFORMATION VCP424418 Sample Number Sample Date 25 Sep 2023 Machine Hours 1110 Oil Hours 1110 Oil Changed Not Changd NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 32.5 CONTAMINATION Silicon ppm 19 Sodium 1 ppm Potassium **4** ppm WEAR METALS Iron ppm 27 Copper ppm 18 Lead ppm **||** <1 Tin ppm 2 🔲 Aluminum ppm 11 Chromium ppm ■ <1 Molybdenum **||** <1 ppm Nickel 2 ppm Titanium 0 ppm Silver 0 ppm Manganese 4 ppm Vanadium ppm 0 **ADDITIVES** 80 Calcium ppm Magnesium 2 ppm Zinc 0 ppm



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC

8418 PALM RIVER ROAD TAMPA, FL US 33619 Contact: JOHN FARDELLA john.fardella@altg.com T: (813)630-0077 F: (813)630-2233

## Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:	VOLVO0093
Unique No:	10709682
Signed:	Wes Davis
Report Date:	24 Oct 2023

203

0

88

Phosphorus

Barium

Boron

ppm

ppm


ppm

## **CONSTRUCTION EQUIPMENT**



GRAPHS

VOLVO



Report Id: VOLVO0093 [WUSCAR] 05987020 (Generated: 10/25/2023 10:49:52) Rev: 1

Contact/Location: JOHN FARDELLA - VOLVO0093