



CONSTRUCTION EQUIPMENT

607758 ATLAS ORGANIC VOLVO L120H 633211 - TRANSMISSION (AUTO)



Sample No: VCP426336
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 607758 ATLAS ORGANIC



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP426336	---	---	---
Sample Date	27 Sep 2023	---	---	---
Machine Hours	1171	---	---	---
Oil Hours	1171	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 28.4	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 14	---	---	---
Sodium	ppm	█ 0	---	---	---
Potassium	ppm	█ 2	---	---	---



WEAR METALS

Iron	ppm	█ 48	---	---	---
Copper	ppm	█ 7	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ 2	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 6	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	64	---	---	---
Magnesium	ppm	█ 2	---	---	---
Zinc	ppm	█ 39	---	---	---
Phosphorus	ppm	█ 174	---	---	---
Barium	ppm	█ 3	---	---	---
Boron	ppm	█ 63	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 10709683
Signed: Wes Davis
Report Date: 24 Oct 2023



CONSTRUCTION EQUIPMENT



GRAPHS

