



# CONSTRUCTION EQUIPMENT

X37246 VOLVO A25G 752299 - COOLANT



**Sample No:** VCP416899  
**Oil Type:** VOLVO COOLANT VCS (YELLOW)  
**Job No:** X37246



## SAMPLE INFORMATION

Sample Number	VCP416899	---	---	---
Sample Date	18 Oct 2023	---	---	---
Machine Hours	0	---	---	---
Sample Status	NORMAL	---	---	---



## COOLANT CONDITION

pH	Scale 0-14	■ 7.14	---	---	---
Reserve Alkalinity	Scale 0-20	---	---	---	---
Nitrites	ppm	■ NT	---	---	---
Percentage Glycol	%	■ 50.6	---	---	---
Freezing Point	°C	■ -35	---	---	---



## CONTAMINATION

Coolant Appearance	normal	---	---	---
Coolant Color	Yllow	---	---	---

**DIPROINDUCA USA LIMITED**  
 2528 MEDINA RD  
 MEDINA, OH  
 US 44256  
 Contact: MATT GILLILAND  
 mgilliland@diproinduca.com  
 T: (225)571-0603  
 F:

## Diagnosis

No corrective action is recommended at this time. The fluid is suitable for further service. There is no indication of any contamination in the coolant. Carboxylate test failed. The glycol level is acceptable. The pH level of this fluid is within the acceptable limits.

**Depot:** DIPMED  
**Unique No:** 10709737  
**Signed:** Jonathan Hester  
**Report Date:** 25 Oct 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

