



CONSTRUCTION EQUIPMENT

SWA386010 RYAN INC VOLVO A25G 752517 - HYDRAULIC SYSTEM



Sample No: VCP433187
Oil Type: AW HYDRAULIC OIL ISO 46
Job No: SWA386010 RYAN INC



SAMPLE INFORMATION

Sample Number	VCP433187	---	---	---
Sample Date	11 Oct 2023	---	---	---
Machine Hours	1397	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	SEVERE	---	---	---

ALTA EQUIPMENT COMPANY
5210 REESE ROAD
DAVIE, FL
US 33314
Contact: N. FACEY
nfacey@altaequipfl.com
T: (954)581-4744
F: (954)583-0318

OIL CONDITION

Visc @ 40°C	cSt	■ 43.9	---	---	---
Acid Number (AN)	mg KOH/g	■ 0.42	---	---	---

CONTAMINATION

Particles >4µm		■ 96590	---	---	---
Particles >6µm		▲ 29891	---	---	---
Particles >14µm		● 1776	---	---	---
ISO 4406:1999 (c)		24/22/18	---	---	---
Silicon	ppm	■ 4	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 1	---	---	---

WEAR METALS

Iron	ppm	■ 5	---	---	---
Copper	ppm	■ 4	---	---	---
Lead	ppm	■ 2	---	---	---
Tin	ppm	■ 0	---	---	---
Aluminum	ppm	■ 2	---	---	---
Chromium	ppm	■ <1	---	---	---
Molybdenum	ppm	■ <1	---	---	---
Nickel	ppm	■ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 0	---	---	---
Vanadium	ppm	0	---	---	---

ADDITIVES

Calcium	ppm	■ 61	---	---	---
Magnesium	ppm	■ 1	---	---	---
Zinc	ppm	■ 431	---	---	---
Phosphorus	ppm	■ 339	---	---	---
Barium	ppm	■ 3	---	---	---
Boron	ppm	■ 0	---	---	---

Diagnosis

We advise that you check all areas where contaminants can enter the system. We advise that you perform a filter service, and use off-line filtration to improve the cleanliness of the system fluid. The air breather requires service. If unrated, we recommend that you replace with a suitable micron rated and/or desiccant air breather. If rated, we recommend that you service/replace the breather. Resample in 30-45 days to monitor this situation. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) AW HYDRAULIC OIL ISO 46. Please confirm. All component wear rates are normal. There is a high amount of particulates (2 to 100 microns in size) present in the oil. The AN level is acceptable for this fluid. The oil is still serviceable provided that the contaminant(s) can be reduced to acceptable levels.

Depot: VOLVO0095
Unique No: 10711762
Signed: Wes Davis
Report Date: 26 Oct 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

