



CONSTRUCTION EQUIPMENT

9825 VOLVO L180H 5472 - TRANSMISSION (AUTO)



Sample No: VCP413653
Oil Type: VOLVO AUTOMATIC TRANSMISSION FLUID AT102
Job No: 9825



SAMPLE INFORMATION

Sample Number	VCP413653	---	---	---
Sample Date	20 Oct 2023	---	---	---
Machine Hours	4170	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

RELIABLE CONTRACTING
 2410 EVERGREEN RD SUITE 200
 GAMBRILLS, MD
 US 21054
 Contact: RUSSELL HATFIELD
 RHATFIELD@RELIABLECONTRACTING.COM
 T: (410)987-1851
 F:



OIL CONDITION

Visc @ 40°C	cSt	█ 27.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 11	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 2	---	---	---

Diagnosis
 Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



WEAR METALS

Iron	ppm	█ 118	---	---	---
Copper	ppm	█ 8	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ <1	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	█ 0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	█ 0	---	---	---



ADDITIVES

Calcium	ppm	█ 75	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 7	---	---	---
Phosphorus	ppm	█ 184	---	---	---
Barium	ppm	█ 4	---	---	---
Boron	ppm	█ 66	---	---	---

Depot: RELMIL
Unique No: 10712229
Signed: Don Baldrige
Report Date: 27 Oct 2023



CONSTRUCTION EQUIPMENT



GRAPHS

