



# CONSTRUCTION EQUIPMENT

619859 TMR VOLVO L180H 619859 (S/N NOT GIVEN) - TRANSMISSION (AUTO)



**Sample No:** VCP419011  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 619859 TMR



## SAMPLE INFORMATION

Sample Number	VCP419011	---	---	---
Sample Date	11 Oct 2023	---	---	---
Machine Hours	0	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Changed	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## OIL CONDITION

Visc @ 40°C	cSt	█ 28.3	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 9	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ 2	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 88	---	---	---
Copper	ppm	█ 4	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ <1	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 5	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 78	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	█ 7	---	---	---
Phosphorus	ppm	█ 183	---	---	---
Barium	ppm	█ 3	---	---	---
Boron	ppm	█ 76	---	---	---

**Depot:** VOLVO0096  
**Unique No:** 10712245  
**Signed:** Wes Davis  
**Report Date:** 26 Oct 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

