

CONSTRUCTION EQUIPMENT
SWA335254 MEIJER CATERPILLAR SR4 5LA03311 - DIESEL ENGI

Sample No: VCP410574

Silicon

Sodium

Potassium

Oil Type: VOLVO ULTRA DIESEL ENGINE OIL 15W40 VDS-3

3

4

6

Job No: SWA335254 MEIJER

ppm

ppm

ppm

SAMPLE I	NFORMATION			
Sample Number	-	VCP410574	 	
Sample Date		25 Sep 2023	 	
Machine Hours		1721	 	
Oil Hours		0	 	
Oil Changed		N/A	 	
Sample Status		NORMAL	 	
OIL CONDI	ITION			
Visc @ 100°C	cSt	14.3	 	
Base Number (BN)	mg KOH/g	■ 9.7	 	
Oxidation (PA)	%	57	 	
CONTAMI	NATION			
Soot %	%	0	 	
Nitration (PA)	%	48	 	
Sulfation (PA)	%	49	 	
Glycol	%	NEG	 	
Fuel	%	<1.0	 	

VOLVO				
WEAR	METALS			
Iron	ppm	2	 	
Copper	ppm	6	 	
Lead	ppm	0	 	
Tin	ppm	-<1	 	
Aluminum	ppm	2	 	
Chromium	ppm	-<1	 	
Molybdenum	ppm	56	 	
Nickel	ppm	■ <1	 	
Titanium	ppm	■ <1	 	
Silver	ppm	■ 0	 	
Manganese	ppm	■ 0	 	
Vanadium	ppm	<1	 	

ADDITIVES							
Calcium	ppm	1014					
Magnesium	ppm	931					
Zinc	ppm	1212					
Phosphorus	ppm	1031					
Barium	ppm	0					
Boron	ppm	■ 3					



ALTA CONSTRUCTION EQUIPMENT LLC

G-3283 S. DORT HIGHWAY BURTON, MI US 48529 Contact: BURTON SERVICE BURTON.SERVICE@ALTAEQUIPMENT.COM

Diagnosis

F:

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO5023 **Unique No:** 10712809 Signed: Sean Felton Report Date: 27 Oct 2023



CONSTRUCTION EQUIPMENT





