

CONSTRUCTION EQUIPMENT X58781 VOLVO EC350EL 310237 - DIESEL ENGINE



Sample No: VCP405789

Oil Type: DIESEL ENGINE OIL SAE 40

Job No: X58781

SAMPLE II	NFORMATION				
Sample Number	-	VCP405789			
Sample Date		23 Oct 2023			
Machine Hours		6414			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
VOLVO	TION				
OIL CONDI	TIUN				
Visc @ 100°C	cSt	13.4			
Base Number (BN)	mg KOH/g	6.7			
Oxidation (PA)	%	59			
CONTAMIN	MULTUR				
_			<u> </u>		
Soot %	%	■0.1			
Nitration (PA)	%	74			
Sulfation (PA)	%	55			
Glycol	%	NEG			
Fuel	%	<1.0			
Silicon	ppm	5			
Sodium	ppm	■3			
Potassium	ppm	4			
VOLVO					
WEAR METALS					
Iron	ppm	5			
Copper	ppm	■ <1			
Lead	ppm	■0			
Tin	ppm	■ <1			
Aluminum	ppm	2			
Chromium	ppm	■ <1			
Molybdenum	ppm	■22			
Nickel	ppm	1			
Titanium	ppm	■54			
Silver	ppm	0			
Manganese	ppm	■0			
Vanadium	ppm	<1			
randdani	PPIII				
VOLVO					
ZAVITIODA ZAVITIONA ZAVITI					
Calcium	ppm	1713			
Magnesium	ppm	■366			
Zinc	ppm	1164			
Phosphorus	ppm	■994			

0

Report Id: SCOSAI [WUSCAR] 05990159 (Generated: 10/27/2023 04:33:14) Rev: 1

ppm

ppm

Barium

Boron



SCOTT EQUIPMENT COMPANY LLC - Saint Rose PO BOX 997 SAINT ROSE, LA US 70087

Contact: DENISE CORVERS dcorvers@scottcompanies.com

T: (504)461-0961 F: (504)461-0970

Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) DIESEL ENGINE OIL SAE 40. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The BN result indicates that there is suitable alkalinity remaining in the oil. The condition of the oil is suitable for further service.

Depot:SCOSAIUnique No:10712821Signed:Wes DavisReport Date:27 Oct 2023



CONSTRUCTION EQUIPMENT





