



# CONSTRUCTION EQUIPMENT

SPM620704 AMG RES SENNOBOGEN 835 835.0.2200 - REAR RIGHT FINAL DRIVE



**Sample No:** VCP420649  
**Oil Type:** GEAR OIL SAE 80W90  
**Job No:** SPM620704 AMG RES



## SAMPLE INFORMATION

Sample Number	VCP420649	---	---	---
Sample Date	19 Oct 2023	---	---	---
Machine Hours	16890	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT CO - ORLAND PARK**  
5000 INDUSTRIAL HWY  
GARY, IN  
US 46406  
Contact: DAVE ENG  
DAVE.ENG@ALTG.COM  
T: (312)350-2560  
F:



## OIL CONDITION

Visc @ 40°C	cSt	█ 161	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 14	---	---	---
Sodium	ppm	█ 12	---	---	---
Potassium	ppm	█ 2	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 220	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 3	---	---	---
Chromium	ppm	█ 8	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 7	---	---	---
Vanadium	ppm	█ 0	---	---	---



## ADDITIVES

Calcium	ppm	█ 38	---	---	---
Magnesium	ppm	█ 6	---	---	---
Zinc	ppm	█ 6	---	---	---
Phosphorus	ppm	█ 307	---	---	---
Barium	ppm	█ <1	---	---	---
Boron	ppm	█ 0	---	---	---

**Depot:** VOLVO8885  
**Unique No:** 10713359  
**Signed:** Don Baldrige  
**Report Date:** 30 Oct 2023



# CONSTRUCTION EQUIPMENT



## VOLVO GRAPHS

