



# CONSTRUCTION EQUIPMENT

SPM620711 VOLVO L70H 624047 - REAR AXLE



**Sample No:** VCP415052  
**Oil Type:** VOLVO WET BRAKE TRANSAXLE OIL  
**Job No:** SPM620711



## SAMPLE INFORMATION

Sample Number	VCP415052	---	---	---
Sample Date	19 Oct 2023	---	---	---
Machine Hours	1920	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

**ALTA EQUIPMENT CO - ORLAND PARK**  
 5000 INDUSTRIAL HWY  
 GARY, IN  
 US 46406  
 Contact: DAVE ENG  
 DAVE.ENG@ALTG.COM  
 T: (312)350-2560  
 F:

## OIL CONDITION

Visc @ 40°C	cSt	█ 41.7	---	---	---
-------------	-----	--------	-----	-----	-----

## CONTAMINATION

Silicon	ppm	█ 14	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 0	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

## WEAR METALS

Iron	ppm	█ 68	---	---	---
Copper	ppm	█ <1	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 1	---	---	---
Chromium	ppm	█ 1	---	---	---
Molybdenum	ppm	█ <1	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---

## ADDITIVES

Calcium	ppm	█ 3508	---	---	---
Magnesium	ppm	█ 24	---	---	---
Zinc	ppm	█ 1580	---	---	---
Phosphorus	ppm	█ 1284	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 109	---	---	---

**Depot:** VOLVO8885  
**Unique No:** 10713415  
**Signed:** Wes Davis  
**Report Date:** 27 Oct 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

