
CONSTRUCTION EQUIPMENT SPM620962 JLG 300215858 - FRONT LEFT FINAL DRIVE



VOLVO

SAMPLE INFORMATION VCP429712 Sample Number Sample Date 20 Oct 2023 Machine Hours 2497 Oil Hours 0 Oil Changed Changed NORMAL Sample Status **OIL CONDITION** Visc @ 40°C cSt 140 CONTAMINATION Silicon ppm 22 Sodium 7 ppm Potassium 0 🔲 ppm WEAR METALS Iron ppm 149 Copper ppm 0 Lead ppm 0 🔲 Tin ppm 0 🔲 Aluminum ppm **||** <1 Chromium ppm 2



ADDITIVES Calcium 56 ppm Magnesium 0 ppm Zinc 11 ppm 822 Phosphorus ppm Barium 0 ppm Boron ppm 165



AJAX ENTERPRISES OF MICHIGAN LLC

830 KIRTS TROY, MI US 48084 Contact: SERVICE MANAGER

T: (248)244-3300 F:

Diagnosis

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.


Depot:	AJATRO
Unique No:	10714492
Signed:	Wes Davis
Report Date:	28 Oct 2023

CONSTRUCTION EQUIPMENT



GRAPHS

VOLVO



Report Id: AJATRO [WUSCAR] 05991830 (Generated: 10/31/2023 12:06:31) Rev: 1

Contact/Location: SERVICE MANAGER - AJATRO