

CONSTRUCTION EQUIPMENT SPM621030 SENNEBOGEN 850E 850.0.3178 - REAR AXLE

Sample No: VCP429507

Oil Type: **GEAR OIL SAE 80W90**

Job No: SPM621030

SAMPLE	INFORMATION			
Sample Number	-	VCP429507	 	
Sample Date		23 Oct 2023	 	
Machine Hours		217	 	
Oil Hours		217	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL COND	ITION			
			 <u> </u>	
Visc @ 40°C	cSt	137	 	
VOLVO				
CONTAM	INATION			
Silicon	ppm	■ 3	 	
Sodium	ppm	■5	 	
Potassium	ppm	□0	 	
	p p · · · ·			
VOLVO	ETALC.			
WEAR MI	FIALS			
Iron	ppm	■ 9	 	
Copper	ppm	6	 	
Lead	ppm	■0	 	
Tin	ppm	■ 0	 	
Aluminum	ppm	0	 	
Chromium	ppm	■0	 	
Molybdenum	ppm	■0	 	
Nickel	ppm	■ 0	 	
Titanium	ppm	<1	 	
Silver	ppm	0	 	
Manganese	ppm	■<1	 	
Vanadium	ppm	0	 	
ADDITIV	ES			
Calcium	ppm	■0	 	
Magnesium	ppm	■ 0	 	
Zinc	ppm	0	 	
Phosphorus	ppm	1464	 	
Barium	ppm	■0	 	
Boron	ppm	146	 	



FERROUS PROCESSING AND TRADING

3400 E LAFAYETTE DETROIT, MI US 48207 Contact: KEITH HALL keith.hall@fpt1.com T:

Diagnosis

F:

Resample at the next service interval to monitor.All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: **FERDET Unique No:** 10714498 Signed: Wes Davis Report Date: 28 Oct 2023

Contact/Location: KEITH HALL - FERDET



CONSTRUCTION EQUIPMENT





GRAPHS

