



# CONSTRUCTION EQUIPMENT

SPM621030 SENNEBOGEN 850E 850.0.3178 - REAR RIGHT FINAL DRIVE



**Sample No:** VCP429509  
**Oil Type:** GEAR OIL SAE 80W90  
**Job No:** SPM621030



## SAMPLE INFORMATION

Sample Number	VCP429509	---	---	---
Sample Date	23 Oct 2023	---	---	---
Machine Hours	217	---	---	---
Oil Hours	217	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

## FERROUS PROCESSING AND TRADING

3400 E LAFAYETTE  
DETROIT, MI  
US 48207

Contact: KEITH HALL  
keith.hall@fpt1.com

T:  
F:



## OIL CONDITION

Visc @ 40°C	cSt	█ 137	---	---	---
-------------	-----	-------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 3	---	---	---
Sodium	ppm	█ 5	---	---	---
Potassium	ppm	█ 0	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.



## WEAR METALS

Iron	ppm	█ 16	---	---	---
Copper	ppm	█ 6	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ 0	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	█ <1	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 0	---	---	---
Magnesium	ppm	█ 0	---	---	---
Zinc	ppm	0	---	---	---
Phosphorus	ppm	█ 1464	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 143	---	---	---

**Depot:** FERDET  
**Unique No:** 10714502  
**Signed:** Wes Davis  
**Report Date:** 28 Oct 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

