

## **CONSTRUCTION EQUIPMENT**

X58730 TADANO GR 1000XL-4 RA 1 1 13 - FRONT RIGHT FINAL DR

Sample No: VCP405809

**Oil Type:** GEAR OIL SAE 80W90

**Job No:** X58730

VOLVO					
SAMPLE INFORMATION					
Sample Number	-	VCP405809			
Sample Date		24 Oct 2023			
Machine Hours		2249			
Oil Hours		0			
Oil Changed		Changed			
Sample Status		NORMAL			
OIL CONDITION					
Visc @ 40°C	cSt	<b>182</b>			
VOLVO					
CONTAMINATION					
Silicon	ppm	<b>11</b>			
Sodium	ppm	<b>■</b> 4			
Potassium	ppm	<b>■</b> <1			
WEAR METALS					
Iron	ppm	■28			
Copper	ppm	<b>■&lt;1</b>			
Lead	ppm	■0			
Tin	ppm	<b>■</b> 0			
Aluminum	ppm	■0			
Chromium	ppm	■1			
Molybdenum	ppm	■2			
Nickel	ppm	■0			
Titanium	ppm	<1			
Silver	ppm	0			
Manganese	ppm	■2			
Vanadium	ppm	0			
VOLVO					
ADDITIV	ES				
Calcium	ppm	■0			
Magnesium	ppm	<b>0</b>			
Zinc	ppm	0			
Phosphorus	ppm	<b>1038</b>			
Barium	ppm	<b>0</b>			
Boron	ppm	<b>211</b>			



SCOTT EQUIPMENT COMPANY LLC - Saint Rose
PO BOX 997
SAINT ROSE, LA
US 70087
Contact: DENISE CORVERS
dcorvers@scottcompanies.com
T: (504)461-0961

F: (504)461-0961

## Diagnosis

Resample at the next service interval to monitor. The fluid was not specified, however, a fluid match indicates that this fluid is (GENERIC) GEAR OIL SAE 80W90. Please confirm.

All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:SCOSAIUnique No:10714507Signed:Wes DavisReport Date:28 Oct 2023



## **CONSTRUCTION EQUIPMENT**





