



CONSTRUCTION EQUIPMENT

621368 CAMO VOLVO A30G 75215 - REAR AXLE



Sample No: VCP412057
Oil Type: VOLVO PREMIUM GEAR OIL 85W-140 GL-5
Job No: 621368 CAMO



SAMPLE INFORMATION

Sample Number	VCP412057	---	---	---
Sample Date	25 Oct 2023	---	---	---
Machine Hours	2067	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	ATTENTION	---	---	---

ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC
 9601 BOGGY CREEK RD
 ORLANDO, FL
 US 32824
 Contact: Robert LaPlante
 robert.laplante@altg.com
 T: (407)508-9736
 F: (407)659-8720



OIL CONDITION

Visc @ 40°C	cSt	▲ 92.8	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 4	---	---	---
Sodium	ppm	■ 2	---	---	---
Potassium	ppm	■ 3	---	---	---



WEAR METALS

Iron	ppm	■ 185	---	---	---
Copper	ppm	■ 31	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 1	---	---	---
Aluminum	ppm	■ 0	---	---	---
Chromium	ppm	■ 4	---	---	---
Molybdenum	ppm	■ 4	---	---	---
Nickel	ppm	■ 2	---	---	---
Titanium	ppm	<1	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	■ 14	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	■ 701	---	---	---
Magnesium	ppm	■ 16	---	---	---
Zinc	ppm	■ 310	---	---	---
Phosphorus	ppm	■ 1338	---	---	---
Barium	ppm	■ 2	---	---	---
Boron	ppm	■ 256	---	---	---

Diagnosis

The oil change at the time of sampling has been noted. Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The oil viscosity is lower than normal. Confirm oil type.

Depot: VOLVO0096
Unique No: 10715863
Signed: Don Baldrige
Report Date: 01 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

