



# CONSTRUCTION EQUIPMENT

621368 CAMO VOLVO A30G 75215 - TRANSMISSION (AUTO)



**Sample No:** VCP412056  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** 621368 CAMO



**ALTA EQUIPMENT/FLAGLER EQUIPMENT LLC**  
 9601 BOGGY CREEK RD  
 ORLANDO, FL  
 US 32824  
 Contact: Robert LaPlante  
 robert.laplante@altg.com  
 T: (407)508-9736  
 F: (407)659-8720



## SAMPLE INFORMATION

Sample Number	VCP412056	---	---	---
Sample Date	25 Oct 2023	---	---	---
Machine Hours	2067	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---



## OIL CONDITION

Visc @ 40°C	cSt	█ 29.7	---	---	---
-------------	-----	--------	-----	-----	-----



## CONTAMINATION

Silicon	ppm	█ 13	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 4	---	---	---



## WEAR METALS

Iron	ppm	█ 24	---	---	---
Copper	ppm	█ 12	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 5	---	---	---
Aluminum	ppm	█ 20	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ <1	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 4	---	---	---
Vanadium	ppm	0	---	---	---



## ADDITIVES

Calcium	ppm	█ 67	---	---	---
Magnesium	ppm	█ 12	---	---	---
Zinc	ppm	█ 0	---	---	---
Phosphorus	ppm	█ 181	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 76	---	---	---

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

**Depot:** VOLVO0096  
**Unique No:** 10715909  
**Signed:** Angela Borella  
**Report Date:** 31 Oct 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

