

## CONSTRUCTION EQUIPMENT 489 VOLVO EWR130E 320192 - FRONT AXLE



Sample No: VCP413009

Oil Type: MOBIL WB 102

**Job No:** 489

SAMPLE	INFORMATION			
Sample Number		VCP413009	 	
Sample Date		18 Oct 2023	 	
Machine Hours		454	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	DITION			
Visc @ 40°C	cSt	<b>81.8</b>	 	
VOLVO	AND TION			
_	MINATION			
Silicon	ppm	■32	 	
Sodium	ppm	■3	 	
Potassium	ppm	<b>7</b>	 	
VOLVO				
WEAR N	METALS			
Iron	ppm	<b>■75</b>	 	
Copper	ppm	<b>■</b> <1	 	
Lead	ppm	<b>1</b>	 	
Tin	ppm	<b>■</b> <1	 	
Aluminum	ppm	<b>■</b> <1	 	
Chromium	ppm	<b>2</b>	 	
Molybdenum	ppm	1	 	
Nickel	ppm	<b>■</b> <1	 	
Titanium	ppm	0	 	
Silver	ppm	0	 	
Manganese	ppm	4	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	/ES			
Calcium	ppm	768	 	
Magnesium	ppm	18	 	
Zinc	ppm	1512	 	
Phosphorus	ppm	765	 	
Barium	ppm	6	 	
Boron	ppm	115	 	

**VCES- VOLVO CONSTRUCTION EQUIPMENT** 

12345 MAPLEVIEW STREET

LAKESIDE, CA US 92040

Contact: Mark Stewart
mark.stewart@vcesvolvo.com

T: X:

F: X:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot:VOLVO4488Unique No:10723074Signed:Wes DavisReport Date:01 Nov 2023



## **CONSTRUCTION EQUIPMENT**





