Sample No: VCP412781

Oil Type: MOBIL WB 102

**Job No:** 489

SAMPLE	INFORMATION	N		
Sample Number		VCP412781	 	
Sample Date		18 Oct 2023	 	
Machine Hours		454	 	
Oil Hours		0	 	
Oil Changed		Changed	 	
Sample Status		NORMAL	 	
OIL CON	NITION			
Visc @ 40°C	cSt	■81.1	 	
VOLVO				
CONTAN	MINATION			
Silicon	ppm	<b>■35</b>	 	
Sodium	ppm	<b>4</b>	 	
Potassium	ppm	<b>2</b>	 	
	pp			
VOLVO	AFTALC			
WEAR N	JE I HLS			
Iron	ppm	<b>67</b>	 	
Copper	ppm	■32	 	
Lead	ppm	<b>1</b>	 	
Tin	ppm	<b>■&lt;1</b>	 	
Aluminum	ppm	<b>2</b>	 	
Chromium	ppm	<b>1</b>	 	
Molybdenum	ppm	0	 	
Nickel	ppm	<b>■&lt;1</b>	 	
Titanium	ppm	2	 	
Silver	ppm	0	 	
Manganese	ppm	2	 	
Vanadium	ppm	0	 	
VOLVO				
ADDITIV	/ES			
Calcium	ppm	722	 	
Magnesium	ppm	18	 	
Zinc	ppm	1520	 	
Phosphorus	ppm	745	 	
Barium	ppm	0	 	
Boron	ppm	106	 	
	PP.II			

**VCES- VOLVO CONSTRUCTION EQUIPMENT** 

12345 MAPLEVIEW STREET

LAKESIDE, CA US 92040

Contact: Mark Stewart mark.stewart@vcesvolvo.com

T: X:

F: X:

## Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO4488
Unique No: 10723081
Signed: Wes Davis
Report Date: 01 Nov 2023



## **CONSTRUCTION EQUIPMENT**





