

## **CONSTRUCTION EQUIPMENT**

W0229316 DREWERY CON VOLVO A45G 353256 - TRANSMISSION

Sample No: VCP412509
Oil Type: DEXRON III

**Job No:** W0229316 DREWERY CON

VOLVO	INFORMATION			
	INFURMATION		<u> </u>	
Sample Number		VCP412509		 
Sample Date		27 Oct 2023		 
Machine Hours		1760		 
Oil Hours		0		 
Oil Changed		Not Changd		 
Sample Status		ABNORMAL		 
OIL COND	ITION			
Visc @ 40°C		= 20.0		
	cSt	■30.8		 
VOLVO				
CONTAM	INATION			
Silicon	ppm	<b>11</b>		 
Sodium	ppm	<b>6</b>		 
Potassium	ppm	<b>2</b>		 
T ottassiai ii	PPIII			
VOLVO				
WEAR M	ETALS			
Iron	ppm	■23		 
Copper	ppm	■10		 
Lead	ppm	<b>1</b>		 
Tin	ppm	<b>2</b>		 
Aluminum	ppm	<b>13</b>		 
Chromium	ppm	■0		 
Molybdenum	ppm	<b>0</b>		 
Nickel	ppm	<b>■1</b>		 
Titanium	ppm	0		 
Silver	ppm	<b>■</b> 0		 
Manganese	ppm	<b>2</b>		 
Vanadium	ppm	0		 
ADDITIV	77			
_				
Calcium	ppm	<b>■</b> 99		 
Magnesium	ppm	<b>15</b>		 
Zinc	ppm	<b>0</b>		 
Phosphorus	ppm	<b>208</b>		 
Barium	ppm	<b>0</b>		 
Boron	ppm	<b>69</b>		 



#### **ROMCO INC**

1350 NE LOOP 820 FORT WORTH, TX US 76106 Contact: CHRIS BITNER CBitner@romco.com T: F: (817)626-8983

### Diagnosis

We advise that you inspect for the source(s) of metal. Resample at the next service interval to monitor. High concentration of visible metal present. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot:VOLVO0081Unique No:10723132Signed:Don BaldridgeReport Date:01 Nov 2023



# **CONSTRUCTION EQUIPMENT**





