



# CONSTRUCTION EQUIPMENT

## W14861 VOLVO A40G 353434 - TRANSMISSION (AUTO)



**Sample No:** VCP441698  
**Oil Type:** VOLVO AUTOMATIC TRANSMISSION FLUID AT102  
**Job No:** W14861



### SAMPLE INFORMATION

Sample Number	VCP441698	---	---	---
Sample Date	27 Oct 2023	---	---	---
Machine Hours	991	---	---	---
Oil Hours	1000	---	---	---
Oil Changed	Not Changed	---	---	---
Sample Status	NORMAL	---	---	---

**HOUSBY HEAVY EQUIPMENT, LLC**  
 4410 SE 4 MILE DR  
 ANKENY, IA  
 US 50021  
 Contact: RANDY VANDERLEEST  
 rvanderleest@housby.com  
 T:  
 F: (515)964-2865



### OIL CONDITION

Visc @ 40°C	cSt	█ 28.0	---	---	---
-------------	-----	--------	-----	-----	-----



### CONTAMINATION

Silicon	ppm	█ 15	---	---	---
Sodium	ppm	█ 6	---	---	---
Potassium	ppm	█ 4	---	---	---



### WEAR METALS

Iron	ppm	█ 25	---	---	---
Copper	ppm	█ 23	---	---	---
Lead	ppm	█ <1	---	---	---
Tin	ppm	█ 3	---	---	---
Aluminum	ppm	█ 13	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 3	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ 0	---	---	---
Manganese	ppm	█ 3	---	---	---
Vanadium	ppm	0	---	---	---



### ADDITIVES

Calcium	ppm	█ 71	---	---	---
Magnesium	ppm	█ 16	---	---	---
Zinc	ppm	█ <1	---	---	---
Phosphorus	ppm	█ 195	---	---	---
Barium	ppm	█ 0	---	---	---
Boron	ppm	█ 74	---	---	---

### Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

**Depot:** VOLVO0080  
**Unique No:** 10723134  
**Signed:** Don Baldrige  
**Report Date:** 01 Nov 2023



# CONSTRUCTION EQUIPMENT



## GRAPHS

