



CONSTRUCTION EQUIPMENT

HERC RENTALS VOLVO A30 753228 - FRONT AXLE



Sample No: VCP365194
Oil Type: NOT GIVEN
Job No: HERC RENTALS



SAMPLE INFORMATION

Sample Number	VCP365194	---	---	---
Sample Date	05 Oct 2023	---	---	---
Machine Hours	996	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
 8418 PALM RIVER ROAD
 TAMPA, FL
 US 33619
 Contact: KENNY HANEY
 khaney@flaglerce.com
 T: (813)630-0077
 F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	■ 88.3	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 7	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 5	---	---	---



WEAR METALS

Iron	ppm	■ 381	---	---	---
Copper	ppm	■ 24	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ <1	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ 8	---	---	---
Molybdenum	ppm	6	---	---	---
Nickel	ppm	■ 4	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	18	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	920	---	---	---
Magnesium	ppm	5	---	---	---
Zinc	ppm	386	---	---	---
Phosphorus	ppm	1408	---	---	---
Barium	ppm	6	---	---	---
Boron	ppm	254	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 10724396
Signed: Wes Davis
Report Date: 02 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

