



CONSTRUCTION EQUIPMENT

HERC RENTALS VOLVO A30 753228 - BOGIE/CENTER AXLE



Sample No: VCP365193
Oil Type: NOT GIVEN
Job No: HERC RENTALS



SAMPLE INFORMATION

Sample Number	VCP365193	---	---	---
Sample Date	05 Oct 2023	---	---	---
Machine Hours	996	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Changed	---	---	---
Sample Status	NORMAL	---	---	---

ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233



OIL CONDITION

Visc @ 40°C	cSt	■ 87.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	■ 12	---	---	---
Sodium	ppm	■ 0	---	---	---
Potassium	ppm	■ 8	---	---	---



WEAR METALS

Iron	ppm	■ 812	---	---	---
Copper	ppm	■ 46	---	---	---
Lead	ppm	■ 0	---	---	---
Tin	ppm	■ 2	---	---	---
Aluminum	ppm	■ <1	---	---	---
Chromium	ppm	■ 17	---	---	---
Molybdenum	ppm	15	---	---	---
Nickel	ppm	■ 9	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	0	---	---	---
Manganese	ppm	27	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	949	---	---	---
Magnesium	ppm	6	---	---	---
Zinc	ppm	396	---	---	---
Phosphorus	ppm	1383	---	---	---
Barium	ppm	6	---	---	---
Boron	ppm	258	---	---	---

Diagnosis

Resample at the next service interval to monitor. Please specify the brand, type, and viscosity of the oil on your next sample. All component wear rates are normal. There is no indication of any contamination in the oil. The condition of the oil is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 10724397
Signed: Wes Davis
Report Date: 02 Nov 2023



CONSTRUCTION EQUIPMENT



GRAPHS

