



CONSTRUCTION EQUIPMENT

HERC RENTALS VOLVO A30 753228 - TRANSMISSION (AUTO)



Sample No: VCP365200
Oil Type: DEXRON III
Job No: HERC RENTALS



ALTA EQUIPMENT/FLAGLER CONSTRUCTION EQUIPMENT LLC
8418 PALM RIVER ROAD
TAMPA, FL
US 33619
Contact: KENNY HANEY
khaney@flaglerce.com
T: (813)630-0077
F: (813)630-2233



SAMPLE INFORMATION

Sample Number	VCP365200	---	---	---
Sample Date	05 Oct 2023	---	---	---
Machine Hours	996	---	---	---
Oil Hours	0	---	---	---
Oil Changed	Not Chngd	---	---	---
Sample Status	NORMAL	---	---	---



OIL CONDITION

Visc @ 40°C	cSt	█ 27.7	---	---	---
-------------	-----	--------	-----	-----	-----



CONTAMINATION

Silicon	ppm	█ 4	---	---	---
Sodium	ppm	█ 4	---	---	---
Potassium	ppm	█ <1	---	---	---



WEAR METALS

Iron	ppm	█ 21	---	---	---
Copper	ppm	█ 5	---	---	---
Lead	ppm	█ 0	---	---	---
Tin	ppm	█ 0	---	---	---
Aluminum	ppm	█ <1	---	---	---
Chromium	ppm	█ 0	---	---	---
Molybdenum	ppm	█ 0	---	---	---
Nickel	ppm	█ 0	---	---	---
Titanium	ppm	0	---	---	---
Silver	ppm	█ <1	---	---	---
Manganese	ppm	█ 1	---	---	---
Vanadium	ppm	0	---	---	---



ADDITIVES

Calcium	ppm	█ 75	---	---	---
Magnesium	ppm	█ 3	---	---	---
Zinc	ppm	█ 36	---	---	---
Phosphorus	ppm	█ 177	---	---	---
Barium	ppm	█ 1	---	---	---
Boron	ppm	█ 68	---	---	---

Diagnosis

Resample at the next service interval to monitor. All component wear rates are normal. There is no indication of any contamination in the fluid. The condition of the fluid is acceptable for the time in service.

Depot: VOLVO0093
Unique No: 10724421
Signed: Don Baldrige
Report Date: 03 Nov 2023



CONSTRUCTION EQUIPMENT



VOLVO GRAPHS

